

CONSERVATION AND RESTORATION WORKS TO THE FATHER MATHEW STATUE, PATRICK'S STREET, CORK



Fig. 1. Detail of the statue, prior to works.



Fig. 2. Detail of the statue, after works.




Fig. 3. Detail of the statue, prior to works.



Fig. 4. Detail of the statue, after works.



Fig. 5. North side of the statue, prior to works.



Fig. 6. North side of the statue, after works.



Fig. 7. West side of the statue, prior to works.



Fig. 8. West side of the statue, after works.



Fig. 9. South side of the statue, prior to works.



Fig. 10. South side of the statue, after works.



Fig. 11. East side of the statue, prior to works.



Fig. 12. East side of the statue, after works.



Fig. 13. Detail of the statue, prior to works.



Fig. 14. Detail of the statue, after works.



The restoration of the Father Mathew Statue could not have been carried out without the invaluable input and support of:

Brendan Watters,
Neil Purkiss, and Southern Access Ltd.

© Eoghan Daltun, sculpture conservator, 2015.